

**United States Environmental Protection Agency
Region VI
POLLUTION REPORT**

Date: Thursday, May 22, 2008

From: Mark Hayes

To: Ragan Broyles, Response and Prevention Branch
Sam Coleman, Superfund Division
Debbie Dietrich, Office of Emergency Management

Subject: Jones Road Ground Water Plume
11600 Jones Rd, Houston, TX
Latitude: 29.9414000
Longitude: -95.5856000

POLREP No.:	4	Site #:	06Nk
Reporting Period:		D.O. #:	
Start Date:	3/15/2007	Response Authority:	CERCLA
Mob Date:	1/2/2008	Response Type:	Time-Critical
Demob Date:		NPL Status:	NPL
Completion Date:		Incident Category:	Removal Action
CERCLIS ID #:	TXN000605460	Contract #	
RCRIS ID #:			

Site Description

The Jones Road Ground Water Plume Site is a ground water plume contaminated with tetrachloroethylene from the former Bell Dry Cleaners at 11600 Jones Road and other potential sources in northwest Harris County, Texas. The plume was originally detected in a public water supply well between Jones Road and Tower Oaks Blvd.

Current Activities

Construction of the waterline is on-going and nearing completion. Daily construction activities are assessed and documented. Scheduling and planning is being done for residents and business owners within the plume boundary to receive water service.

Crews are working to keep streets clear and make repairs of driveways, mailboxes and such that are damaged during the work.

Planned Removal Actions

None at this time. Remedial actions are being implemented.

Next Steps

Scheduling and planning for residential and commercial service connections.

Estimated Costs *

	Budgeted	Total To Date	Remaining	% Remaining
Extramural Costs				
Intramural Costs				
Total Site Costs	\$0.00	\$0.00	\$0.00	0.00%

* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.